

Product Code . JL-MLLE-9169

Current To Pressure Measurement Trainer



Description

Current To Pressure Measurement Trainer

Current to Pressure Trainer.

This setup comprises of a I to P converter fitted on a base.

A current source with digital display is provided to excite the I to P converter.

Two pressure gauges are fitted one at the input side and the other at the output of the I to P converter.

A constant air supply should be provided to the system at 20 Psi Pressure from a standard compressor.
