

Description

Hand Held Tune-Up Analyzer

Large display:-

3-3/4 digit app. 4000 count, auto arranging meter with analog bar graph and additional setting symbol.

Record max. and min.

RS-232 interface to PC

Combine trig± with duty cycle or pulse width

DC and AC Volts:-

400mV, 4V, 40V, 400V, 500V.

Resistance:-

400?, 4K?, 40K?, 400K?, 4M?, 40M?.

Continuity buzzer

Diode test to check alternators, relays, solenoids.

K-type temperature probe should be included.

Currents DC and AC Current:-]

40 mA, 400 mA, 20 A