



Product Code . JL-VOVLACOS-1101

Measurement of Peak, Average and RMS Value of a AC Signal

Description

Measurement of Peak, Average and RMS Value of a AC Signal

Instrument consists of Sine Wave generator, Step Down Transformer, Circuit Diagram for Peak & average Value measurement Printed and connections brought on terminals.

Dimension 10"x8"x4".

Contact JLab Export for your Educational School Science Lab Equipments. We are best school lab equipments supplier, school lab export, school lab exporter, school laboratory equipment manufacturers, school laboratory equipment suppliers, school science equipments.
