

Product Code . JL-PEAWE-8718

MIG Welding Machine



Description

MIG Welding Machine

Description:-

Mig 250 / 40C Power Source.

Wire Feeder

Set of cables and Hoses

Ground Cable

Interconnecting Cable

Wire feeder input Cable

Shielding Gas Hose

Voltage	415V, 3 Phase, 50 Hz	415V, 3 Phase, 50 Hz
Current (full load)	11 Amps	15 Amps
Power factor	0.9	0.9

Fuses	16 amps	25 Amps
Output Current (100% duty cycle)	200 Amps	320 Amps
Output Current (60% duty sale)	250 Amps	400 Amps
Open Circuit Voltage	15-36 Volts	15-42 Volts

Contact JLab Export for your Educational School Science Lab Equipments. We are best scientific laboratory equipments manufacturer, scientific laboratory equipments supplier, technical educational equipment exporter, technical educational equipment manufacturer, technical educational equipment supplier, technical educational equipments exporter.
